

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: FC2G to S-ATA 8 CHL. (i80321)(7320)
For: SB-2803FA series.

Important notes:

- 1. Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
- 2. Please update BOOT module before upgrade this version.**
 - (1) Upgrade Boot module: 7320BOOTxxxxx.bin**
 - (2) Upgrade firmware: 7320xxxxxx.bin**

	Last Version	New Version
Version No.	1.39 060317	1.42 061013
Date		December 27, 2006
New		1. Added multiple volume check at one time (HTTP only). 2. Added SCRUB bad block and REPAIR parity function. 3. Added Event and warning if incomplete RAID Set discovered. 4. Added completion aborted and stopped events for migration, rebuilding and initialization. 5. New rescue mode. 6. Added HDD timeout option (12, 17, 22, 27 and 32).
Fixed		1. Fixed Hitachi HD issue (Raid locked up). 2. Fixed WD4000YR detect problem (power on/off). 3. Fixed heavy loading filter HDD temperature issue.
Modification		1. The LBA address is logged for reference when Power loss during migration, rebuilding and initialization. 2. Change bad block generation to compatible with Seagate. 3. Change the Voltage high limit to 5.4V for 5V. 4. Tried Fabric first, switch to P2P if N-Port found.
Removed		