Firmware Release History

Model: U320/FC2G to SATA 16 CHL. (80321)(8990)

Version	Firmware Date	Release Date	Notes
6.07a	06/13/2005	08/29/2005	1. Fixed Host cannot access when Array with online-init is in progress. 2. Fixed PCI or SATA error when Array 1 is performing online-init and concurrently creating Array 2. 3. FC: Fixed Dual FC problem on Mac OS X 10.4. 4. Clear warning message automatically when BBM temperature is less than 45'C.
6.06a	01/17/2005	03/01/2005	1. Support 16 bytes CDB. (Over 2TB) 2. FC: Add register FC-4 Types. 3. Modify support disk sequence power up. 4. Fixed disk scrubbing and clone problems. 5. Fixed GUI problems for disk Scrub & Clone. 6. Modify hot plug timing for compatibility issue. 7. Correct the message of bad sector occurred while rebuilding from 'remapped' to 'data unrecoverable'. 8. Remove "disk offset" from menu. 9. Modify BBM over temp from 45 degree to 55 degree. 10. Move IDE timeout from special menu to RAID function. 11. UPS port pin re-definition.
6.04a	10/12/2004	11/01/2004	1. Support Disk Scrubbing function. 2. Support Disk Clone & SMART function. 3. Support Disk Self Test function. 4. Fixed Multiple-ID issue. 5. Fixed PCI interrupt error.
6.03a	09/08/2004	09/16/2004	1. Support up to 16TB per slice. 2. Fixed Solaris OS recognize capacity over

			500GB.
			3. Improve the Hitachi 400GB compatibility issue.
			4. Fixed disk remap issue.
			5. Fixed BBM data about issue.
6.02a	06/03/2004	06/09/2004	1. Enhance performance.
			2. Support online (background) init Array.
			3. Support NRAID function.
			4. Support new GUI command set and page data.
			5. Fixed problem of FAX data cannot over 1 page.
			6. Expand some menu item for fibre "SAN mask" setting. (Host 1-32, LUN 0-127).
			7. Modify BBM progress and its display messages.
6.01a	03/23/2004	04/08/2004	1. Fixed JBOD issue for LSI HBA card.
			2. Reduce Data Abort issue.
			3. Improve the SATA HDD compatibility.
			4. Support new Flash type.
6.00a	02/06/2004	02/11/2004	1. Initial release.