

Proware Technology Corp.  
Technical Support Team  
Firmware Release Notes

Model: FC4G to SATA-2 42 CHL. (S/D) (PPC 440e)  
For: EP-4429(S/D)-F4A3 Series.

**Important Notes:**

- 1. Firmware version before 1.21: \*\*\* Please upgrade prerequisites firmware 1.21 for Controller (EP901045) first. \*\*\***
- 2. Please upgrade firmware for “Controller”, “Expander” and “Bottom Board Expander”.**
- 3. Please upgrade proSES-II firmware via RS-232.**
- 4. Please install new version of proRAIDManager.**

**A. Controller (EP901045)**

**=== Prerequisites firmware 1.21 ===**

<b>1.31 (03/18/2009)</b>	
<b>Release Date</b>	<b>March 20, 2009</b>
<b>New</b>	<ol style="list-style-type: none"><li>1. Reset counters button to FC Port Statistics screen.</li><li>2. Node name same / diff dropdown to Port Setup screen.</li><li>3. Ability to use '!s' in LV names.</li></ol>
<b>Fixed</b>	<ol style="list-style-type: none"><li>1. Fixed RAID ownership screen displays N/A if invalid preferred owner is specified.</li><li>2. Fixed preventing some causes of broken pipe errors.</li><li>3. Fixed memory leak in web GUI code.</li><li>4. Fixed cache issue for random reads.</li><li>5. Fixed valid product names for upgrading expander firmware.</li><li>6. Flash writing improvements to prevent board resets caused by configuration changes.</li><li>7. Fixed browser timeouts in some web GUI.</li></ol>

**B. Expander (EP901060)**

<b>0407</b>	
<b>Release Date</b>	<b>March 20, 2009</b>
<b>Fixed</b>	<ol style="list-style-type: none"><li>1. Improve SATA flow control behaviors, those externs functions were inline and speed optimization.</li></ol>

Proware Technology Corp.  
Technical Support Team

**C. Bottom Board Expander (EP914242)**

<b>111</b>	
<b>Release Date</b>	<b>November 28, 2008</b>

**D. proSES-II (EP95601)(SES2)**

<b>1.19</b>	
<b>Release Date</b>	<b>March 20, 2009</b>
<b>Fixed</b>	1. Fixed incorrect reading on low temperature.

**E. proSES (EP96601)(SES)**

**=== NO IP DISPLAY ON LCD ===**

<b>1.19</b>	
<b>Release Date</b>	<b>March 20, 2009</b>
<b>Fixed</b>	1. Fixed incorrect reading on low temperature.

**F. proRAIDManager**

<b>P1.5.37</b>	
<b>Release Date</b>	<b>March 20, 2009</b>
<b>New</b>	1. Enable "SEARCH" for web GUI controller firmware version.