

Proware Technology Corp.  
 Technical Support Team  
 Firmware Release Notes

**Model: FC2G to S-ATAII 16 CHL. (i80321)(7360)**  
**For: SB-3163FA series.**

**Important notes:**

- 1. Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
- 2. Please update BOOT module before upgrade this version.**
  - (1) Upgrade Boot module: 7360BOOTxxxxx.bin**
  - (2) Upgrade firmware: 7360xxxxxx.bin**
- 3. For 1.32 and early version, please also update LSI Fibre Chip firmware after upgrade this version.**
  - (1) Upgrade Boot module: 7360BOOTxxxxx.bin**
  - (2) Upgrade firmware: 7360xxxxxx.bin**
  - (3) Upgrade LSI Chip: LSIMPTxxxxx.bin**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>1.39 060524</b>	<b>1.42 061013</b>
<b>Date</b>		<b>December 27, 2006</b>
<b>New</b>		1. Added HDD timeout option (12, 17, 22, 27 and 32). 2. Added Persistent Reservation commands support.
<b>Fixed</b>		1. Fixed bug for command abortion. 2. Fixed heavy loading filter HDD temperature issue.
<b>Modification</b>		1. Change bad block generation to compatible with Seagate. 2. Change the Voltage high limit to 5.4V for 5V. 3. Tried Fabric first, switch to P2P if N-Port found.
<b>Removed</b>		