

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: FC4G to SATA-II 8 CHL. (80321)(7520)
For: SB-2803-F4A3 series.

Important notes:

- 1. For firmware version 1.39 and earlier, please update TRANSITION firmware first and restart controller,**
 - (1) Upgrade TRANSITION firmware: 7520-transition.bin
 - (2) Restart
 - (3) Upgrade Boot module: 7520BOOTxxxxx.bin
 - (4) Upgrade firmware: 7520xxxxxxx.bin
- 2. Firmware 1.42 and later could not downgrade to earlier version.**

	Last Version	New Version YYMMDD
Version	1.45 080314	1.46 090106
Boot Code Version	1.45 080314	1.46 090106
Release Date		June 5, 2009
New		1. Fixed NTP error after 2009. 2. Fixed Solaris 10 inquiry page 0x83 issue. 3. Fixed Solaris LBA overflow issue. 4. Improved SNMP agent request overflow issue. 5. Exclude super password via TELNET for security reason.
Fixed		1. Modified the LOGIN event from ERROR to WARNING.
Modification		
Removed		