

Proware Technology Corp.

Technical Support Team

Firmware Release Notes

Model: FC4G to SATA-II 8 CHL. (80321)(7520)

For: SB-2803-F4A3 series.

Important notes:

1. For firmware version 1.39 and earlier, please update **TRANSITION** firmware first and restart controller,
 - (1) Upgrade **TRANSITION** firmware: 7520-transition.bin
 - (2) Restart
 - (3) Upgrade **Boot** module: 7520BOOTxxxxx.bin
 - (4) Upgrade **firmware**: 7520xxxxxx.bin
2. Firmware 1.42 and later could not downgrade to earlier version.

	Last Version	New Version
Version	1.42 061013	1.45 080314
Boot Code Version	1.42 061013	1.45 080314
Release Date		April 10, 2008
New		1. Added HDD Spin Down function. (MAID). 2. Added Off-Line RaidSet for on-line roam member disks to another subsystem. 3. Added auto hot spare support (across power cycle). 4. Added support MTRON SSD.
Fixed		1. Fixed Seagate 750G/500G SATA disk timeout issue. 2. Fixed WD 1TB drive detection issue. 3. Fixed IE7 update firmware problem under Vista. 4. Fixed BBM boot issue. 5. Fixed RAID 1 and 0+1 issue.
Modification		
Removed		