Proware Technology Corp. Technical Support Team Firmware Release Notes

Model: FC4G to S-ATAII 16 CHL. (i80321)(7560)

For: SB-3163-F4A3 series.

Important notes:

1. For firmware version 1.39 and earlier, please update TRANSITION firmware first and restart controller,

(1) Upgrade TRANSITION firmware: 7560-transition.bin

(2) Restart

(3) Upgrade Boot module: 7560BOOTxxxxx.bin

(4) Upgrade firmware: 7560xxxxxx.bin

2. Firmware 1.42 and later could not downgrade to earlier version.

	Previous Version	New Version YYMMDD
Version	1.45 080314	1.46 090106
Boot Code Version	1.45 080314	1.46 090106
Release Date		March 27, 2009
New		
Fixed		1. Fixed NTP error after 2009.
		2. Fixed Solaris 10 inquiry page
		0x83 issue.
		3. Fixed Solaris LBA overflow issue.
		4. Improved SNMP agent request
		overflow issue.
		5. Exclude super password via
		TELNET for security reason.
Modification		1. Modified the LOGIN event from
		ERROR to WARNING.
Removed		