

Proware Technology Corp.  
Technical Support Team  
Firmware Release Notes

**Model: U3 SCSI/FC2G to ATA-133 14 CHL. (i80303)(8910)**

**For: Simbolo SB/SN-3140, SB-3140FC series. (Multiple Array)**

**Important notes:**

- 1. The multiple arrays version does not compatible with single array version. All data will be destroying when upgrade from single array version.**
- 2. Please backup your original data before you upgrade from single array version.**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>4.20M</b>	<b>4.21M</b>
<b>Date</b>		<b>January 23, 2006</b>
<b>New</b>		
<b>Fixed</b>		
<b>Modification</b>		1. Modify Array rebuild mechanism to avoid disk remap when reading data from member disk failed. (A) Bypass the remap mark for rebuilt disk. (B) Display alert messages of "DISK: #? Blkno=0x???? DATA cannot be recovered!!" on console.
<b>Removed</b>		