

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: U3 SCSI/FC to Serial ATA 16 CHL. (i80303)(8960)**  
**For: SB-3160SA(T)/FA(T) Series.**

**Important notes:**

**This version could not downgrade back to 6.03a & early version. The Array configuration is different with early version.**

|                     | <b>Last Version</b> | <b>New Version</b>   |
|---------------------|---------------------|--|
| <b>Version No.</b>  | <b>6.10a</b>        | <b>6.12a</b>   |
| <b>Date</b>         |                     | <b>September 12, 2005</b>  |
| <b>New</b>          |                     | 1. Display bad block active count number on the system statistic function.<br>2. Support new flash type. |
| <b>Fixed</b>        |                     | 1. Fixed DV failed.<br><b>FC:</b><br>1. Fixed dual channel for Mac OS X issue.                           |
| <b>Modification</b> |                     | 1. Force bad block re-map use disk itself first.   |
| <b>Removed</b>      |                     |  |