

Proware Technology Corp.  
 Technical Support Team  
 Firmware Release Notes

**Model: iSCSI(1Gbps) 4 ports to SAS 16 CHL. (IOP342)  
 For: SB-3164-G1S3 Series.**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.(DC)</b>	<b>1.1.0</b>	<b>1.1.4</b>
<b>Firmware Date</b>	<b>200804181300</b>	<b>200812241100</b>
<b>Release Date</b>		<b>January 15, 2009</b>
<b>New</b>		<ol style="list-style-type: none"> <li>1. Added "Filter" for "user" account.</li> <li>2. Added backend I/O timeout.</li> <li>3. Added support ping with large MTU.</li> <li>4. Added UDV/VD block size to 8, 16, 32 and 64K.</li> <li>5. Added background I/O rate option.</li> <li>6. Added display JBOD firmware version on UI.</li> <li>7. Added JBOD fans and power events log.</li> </ol>
<b>Fixed</b>		<ol style="list-style-type: none"> <li>1. Fixed "Time Zone" issue on UI.</li> <li>2. Fixed error on Windows Server 2008 Cluster (32bit).</li> <li>3. Fixed CHAP issue on UI.</li> <li>4. Fixed LUN issue on VMWare ESX with QLA4052.</li> <li>5. In Web UI, it has no error message to set the dedicated spare disk fail.</li> <li>6. Fixed node name become blank issue.</li> <li>7. Fixed Web UI login fail sometime.</li> </ol>
<b>Modification</b>		<ol style="list-style-type: none"> <li>1. Disk NCQ can be disable.</li> <li>2. Enable/Disable disk property.</li> </ol>
<b>Removed</b>		