

## Firmware Release History

**Model: U320/FC2G to SATA 8 CHL. (80321)(89200)**

Version	Firmware Date	Release Date	Notes
1.06a	06/10/2005	08/29/2005	<ol style="list-style-type: none"> <li>1. Fixed Host cannot access when Array with online-init is in progress.</li> <li>2. Fixed PCI or SATA error when Array 1 is performing online-init and concurrently creating Array 2.</li> <li>3. FC: Fixed Dual FC problem on Mac OS X 10.4.</li> <li>4. Clear warning message automatically when BBM temperature is less than 45'C.</li> </ol>
1.05a	03/17/2005	07/21/2005	<ol style="list-style-type: none"> <li>1. Fixed UPS port defines issue.</li> </ol>
1.04a	01/17/2005	03/01/2005	<ol style="list-style-type: none"> <li>1. Support 16 bytes CDB. (Over 2TB)</li> <li>2. FC: Add register FC-4 Types.</li> <li>3. Fixed disk scrubbing and clone problems.</li> <li>4. Fixed GUI problems for disk Scrub &amp; Clone.</li> <li>5. Modify disk sequence power on.</li> <li>6. Modify hot plug timing for disk compatibility issue.</li> <li>7. Modify BBM over temp from 45 degree to 55 degree.</li> <li>8. Move IDE timeout from special menu to RAID function.</li> <li>9. Correct the message of bad sector occurred while rebuilding from 'remapped' to 'data unrecoverable'.</li> <li>10. Remove "disk offset" from menu.</li> </ol>
1.03a	10/20/2004	11/26/2004	<ol style="list-style-type: none"> <li>1. New function "<b>Disk Scrubbing</b>".</li> <li>2. New function "<b>Disk Clone</b>" &amp; "<b>SMART Mode</b>".</li> <li>3. New function "<b>Disk Self Test</b>".</li> <li>4. Add "IDE Timeout" menu option in the Special menu.</li> <li>5. Fixed Multiple-ID issue.</li> </ol>

1.00a	NA	06/08/2004	1. Initial release.
-------	----	------------	---------------------