

Firmware Release History

Model: U320/FC2G to SATA 16 CHL. (80321)(89230)

Version	Firmware Date	Release Date	Notes
2.06a	06/10/2005	08/29/2005	<ol style="list-style-type: none"> 1. Fixed Host cannot access when Array with online-init is in progress. 2. Fixed PCI or SATA error when Array 1 is performing online-init and concurrently creating Array 2. 3. FC: Fixed Dual FC problem on Mac OS X 10.4. 4. Clear warning message automatically when BBM temperature is less than 45'C.
2.05a	03/17/2005	07/21/2005	<ol style="list-style-type: none"> 1. Fixed UPS port defines issue.
2.04a	01/17/2005	03/01/2005	<ol style="list-style-type: none"> 1. Support 16 bytes CDB. (Over 2TB) 2. FC: Add register FC-4 Types. 3. Fixed disk scrubbing and clone problems. 4. Fixed GUI problems for disk Scrub & Clone. 5. Modify disk sequence power on. 6. Modify hot plug timing for disk compatibility issue. 7. Modify BBM over temp from 45 degree to 55 degree. 8. Move IDE timeout from special menu to RAID function. 9. Correct the message of bad sector occurred while rebuilding from 'remapped' to 'data unrecoverable'. 10. Remove "disk offset" from menu.
2.03a	10/20/2004	11/26/2004	<ol style="list-style-type: none"> 1. New function "Disk Scrubbing". 2. New function "Disk Clone" & "SMART Mode". 3. New function "Disk Self Test". 4. Add "IDE Timeout" menu option in the Special menu. 5. Fixed Multiple-ID issue.

2.00a	NA	06/08/2004	1. Initial release.
-------	----	------------	---------------------