

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: U320 SCSI to S-ATA-II 8 CHL. (i80321)(6320)
For: SB-2803SA series.

Important notes:

- 1. Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
- 2. Please update BOOT module before upgrade this version.**
(1) Upgrade Boot module: 6320BOOTxxxxx.bin
(2) Upgrade firmware: 6320xxxxxx.bin

	Last Version	New Version YYMMDD
Version	1.45 080314	1.46 090106
Boot Code Version	1.45 080314	1.46 090106
Release Date		March 2, 2009
New		1. Added display of IU status.
Fixed		1. Fixed NTP error after 2009. 2. Fixed Solaris 10 inquiry page 0x83 issue. 3. Fixed Solaris LBA overflow issue. 4. Fixed ATTO U320 SCSI issue. 5. Improved SNMP agent request overflow issue. 6. Exclude super password via TELNET for security reason.
Modification		1. Modified the LOGIN event from ERROR to WARNING.
Removed		