Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: FC2G to EIDE 16 CHL. (80321)(7160)
For: SB-3160FI series.

Important notes:
1. **Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
2. **Please update BOOT module first.**
   (1) Upgrade Boot module: 7160BOOTxxxxx.bin
   (2) Upgrade firmware: 7160xxxxxx.bin
3. **For 1.31 and early version, please update LSI Fibre Chip firmware after upgrade this version.**
   (1) Upgrade Boot module: 7160BOOTxxxxx.bin
   (2) Upgrade firmware: 7160xxxxxx.bin
   (3) Upgrade LSI Chip: LSIMPTxxxxx.bin

	Last Version	New Version
Version No.	1.36 050411	1.39 060308
Date		April 13, 2006
New		1. Added Stagger power on control function. 2. Added RAID 1(1+0) with initialization function.
Fixed		1. Fixed Ethernet problem (Browser and Telnet can not connect). 2. Fixed Hitachi 500G HDS725050KLAT80 issue.
Modification		1. Display SMART status in drive status. 2. Mail SMTP port settable.
Removed		