Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: U3 SCSI/FC2G to ATA-133 14 CHL. (i80303)
For: Simbolo SB/N-3140 Series, SB-3140FC series.

Important note:

For customers who have installed 512MB cache to upgrade from 4.05A or early version:

1. Please shutdown the RAID.
2. Remove all disks from slots.
3. Power up the RAID then write down the stripe size at now and set the stripe size to '8'.
4. Download the firmware.
5. Reset the stripe size to previously then power off the RAID.
6. Put all disks back then power up.

	Last Version	New Version
Version No.	4.19A	4.21A
Date		April 8, 2004
New		
Fixed		1. Fix FreeBSD issue. 2. HDD status not match between LCD and statistics. 3. Address/Type error occurs when erase NVRAM and restart controller after remove a disk of RAID group. 4. Fix exception problem while encounter heavy small I/O. 5. Fix serial number not visible from Veritas. 6. Fix for 'Winthrax' error under degraded mode.
Modification		1. Support new flash type.
Removed		