Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: iSCSI(1Gbps) 2 ports to SATA-II 8/12/16 CHL. (i80341/800)(P150C)
For: SB-2804-G1A3, SB-2124-G1A3, SB-3164E-G1A3 Series.

Important note:

1. **The version did not compatible with firmware 1.0.0.**
2. **Upgrades from 1.0.0 please backup your data first.**

	Previous Version	New Version
Version No.	**1.1.4**	**1.1.6**
Date Code	**200812121700**	**200906251800**
Release Date		**August 3, 2009**
New		1. Added display hard drive firmware on GUI. 2. Added without "initialization" option.
Fixed		1. Fixed naming with special characters hand up issue. 2. Fixed "Company" and "Product" name disappeared issue. 3. Fixed console LUN more than 255 issue. 4. Fixed abnormal attached 1025th LUN. 5. Fixed long event log did not show complete in console. 6. Fixed RAID5 with strip size 4K stop initialize. 7. Fixed hot plug issue for Hitachi HDE721010SLA330. 8. Fixed WS2003 MSCS issue.
Modification		1. The default SNMP events level change to "Warning and Error".
Removed		