Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: iSCSI(1Gbps) 2 ports to SATA-II 16 CHL. (i80341/800)
For: SB-3164E-G1A3 Series.

	Last Version	New Version
Version No.(DC)	1.1.3 (200809261100)	1.1.4 (200812121700)
Date		**January 14, 2009**
New		1. Added "Filter" for "user" account. 2. Added backend I/O timeout. 3. Added support ping with large MTU. 4. Added UDV/VD block size to 8, 16, 32 and 64K. 5. Added background I/O rate option.
Fixed		1. Fixed "Time Zone" issue on UI. 2. Fixed error on Windows Server 2008 Cluster (32bit). 3. Fixed CHAP issue on UI. 4. Fixed LUN issue on VMWare ESX with QLA4052.
Modification		1. Disk NCQ can be disable. 2. Enable/Disable disk property.
Removed		