

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: iSCSI(1Gbps) 2 ports to SATA-II 12 CHL. (i80341/800)
For: SB-2124-G1A3 Series.

| | Last Version | New Version |
|------------------------|-----------------------------|---|
| Version No.(DC) | 1.1.3 (200809261100) | 1.1.4 (200812121700) |
| Date | | January 14, 2009 |
| New | | <ol style="list-style-type: none"> 1. Added "Filter" for "user" account. 2. Added backend I/O timeout. 3. Added support ping with large MTU. 4. Added UDV/VD block size to 8, 16, 32 and 64K. 5. Added background I/O rate option. |
| Fixed | | <ol style="list-style-type: none"> 1. Fixed "Time Zone" issue on UI. 2. Fixed error on Windows Server 2008 Cluster (32bit). 3. Fixed CHAP issue on UI. 4. Fixed LUN issue on VMWare ESX with QLA4052. |
| Modification | | <ol style="list-style-type: none"> 1. Disk NCQ can be disable. 2. Enable/Disable disk property. |
| Removed | | |