

Firmware Release History

Model: iSCSI(1Gbps) x 4 to SAS 16 CHL. (IOP342)(P200C)

Version	Firmware Date	Release Date (MM/DD/YYYY)	Notes
1.1.6	200906251800	08/24/2009	<ol style="list-style-type: none"> 1. Added display hard drive firmware on GUI. 2. Added without "initialization" option. 3. Added SAS "Expander Settings" option for "Power User". 4. Fixed naming with special characters hand up issue. 5. Fixed "Company" and "Product" name disappeared issue. 6. Fixed console LUN more than 255 issue. 7. Fixed abnormal attached 1025th LUN. 8. Fixed long event log did not show complete in console. 9. Fixed RAID5 with strip size 4K stop initialize. 10. Fixed hot plug issue for Hitachi HDE721010SLA330. 11. Fixed WS2003 MSCS issue. 12. Fixed upgrade firmware then JBOD disk show as "Free". 13. Fixed QLogic QLA4052C with more than 2 nodes name issue. 14. Fixed "Host (iSCSI node name)" empty issue. 15. The default SNMP events level change to "Warning and Error".
1.1.4	200812241100	01/15/2009	<ol style="list-style-type: none"> 1. Added "Filter" for "user" account. 2. Added backend I/O timeout. 3. Added support ping with large MTU. 4. Added UDV/VD block size to 8, 16, 32 and 64K. 5. Added background I/O rate option. 6. Added display JBOD firmware

			<p>version on UI.</p> <p>7. Added JBOD fans and power events log.</p> <p>8. Fixed “Time Zone” issue on UI.</p> <p>9. Fixed error on Windows Server 2008 Cluster (32bit).</p> <p>10.Fixed CHAP issue on UI.</p> <p>11.Fixed LUN issue on VMWare ESX with QLA4052.</p> <p>12.In Web UI, it has no error message to set the dedicated spare disk fail.</p> <p>13.Fixed node name become blank issue.</p> <p>14.Fixed Web UI login fail sometime.</p> <p>15.Disk NCQ can be disable.</p> <p>16.Enable/Disable disk property.</p>
1.1.0	200804181300	05/23/2008	<p>1. Added French GUI support.</p> <p>2. Fixed GUI hand on at “Import in progress..” when click config import.</p> <p>3. Fixed trunk issue on RHAS4.</p> <p>4. Fixed cannot set spare in console. (RAID 0+1).</p> <p>5. Changed time zone setting style to Windows like.</p> <p>6. Changed MTU to Jumbo Frame and for Enable/Disable.</p> <p>7. Changed thermal threshold to 85 degree for SAS chip.</p>
1.0.2	200712101500	12/13/2007	<p>1. Initial release.</p>