Proware Technology Corp. Technical Support Team

Firmware Release Notes

Model: iSCSI(1Gbps) 4 ports to SAS 16 CHL. (IOP342)

For: SB-3164E-G1S3 Series.

	Last Version	New Version
Version No.(DC)	1.0.2 (200809191500)	1.0.3 (200812121700)
Date		January 14, 2009
New		1. Added "Filter" for "user"
		account.
		Added backend I/O timeout.
		3. Added support ping with large MTU.
		4. Added UDV/VD block size to 8, 16, 32 and 64K.
		5. Added background I/O rate
Cisco al		option.
Fixed		Fixed "Time Zone" issue on UI.
		2. Fixed error on Windows Server 2008 Cluster (32bit).
		3. Fixed CHAP issue on UI.
		4. Fixed LUN issue on VMWare
		ESX with QLA4052.
		5. In Web UI, it has no error
		message to set the dedicated spare disk fail.
Modification		Disk NCQ can be disable.
		2. Enable/Disable disk property.
Removed		