

Firmware Release History

Model: FC2G SCSI to EIDE 16 CHL. (80321) (7160)

Version	Boot Code	Release Date	Notes
1.39-060308	1.39-051206	04/13/2006	<p>Update from 1.36 and earlier, Ethernet configuration must be saved again.</p> <ol style="list-style-type: none"> 1. Added Stagger power on control function. 2. Added RAID 1(1+0) with initialization function. 3. Fixed Ethernet problem (Browser and Telnet can not connect). 4. Fixed Hitachi 500G HDS725050KLAT80 issue. 5. Display SMART status in drive status. 6. Mail SMTP port settable.
1.36-050411	1.36-050411	04/13/2005	<ol style="list-style-type: none"> 1. Add 5 seconds delay for battery backup support. 2. Support 16/12 bytes CDB and Windows large block. 3. Add 'Timeout' option. 4. Add 'Retry times' option. 5. Add 'Error statistic' report. 6. Support WD RE model special function. 7. TCP/IP timeout change to 3 minutes. 8. Send RST to client if TCP connection over 3 minutes. 9. Fixed disk geometry of mode sense parameter for Solaris. 10. Use NEW_SMART function for disks. 11. Improve random access

			<p>performance.</p> <p>12. SNMP parameter can be modify for, sysContact.0, sysLocation.0 and sysName.0</p>
1.34-041226	1.34-040929	12/21/2004	1. Fixed over 2TB issue.
1.34-041026	1.34-040929	12/13/2004	<p>1. Add 2TB function.</p> <p>2. Add EXPAND_VOLUME_CAPACITY support.</p>
1.33-040928	1.33-040928	11/11/2004	<p>1. Add telnet support.</p> <p>2. Auto detects HBA WWNN or WWPN.</p> <p>3. Fixed RAID 5 with 2 disks fail issue.</p> <p>4. Fixed Fibre write through mode issue.</p> <p>5. Fixed WS2003 clustering with fabric switch issue.</p> <p>6. Modify BOOT module.</p> <p>7. Support both WWNN & WWPN for SAN Masking.</p>
1.31-040531	NA	05/28/2004	1. Initial release.