

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: FC4G to S-ATAII 16 CHL. (PPC440)(8560)
For: SB-3163E-F4A3, SB-3163S-F4A3 series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 8560BOOTxxxxx.bin**
 - (2) Upgrade firmware: 8560xxxxxx.bin**

	Last Version	New Version
Version	1.46 090206	1.47 090714
Boot Code Version	1.46 090106	1.47 090625
Release Date		December 10, 2009
New		1. Added Shutdown function. 2. Added HDD APM support.
Fixed		
Modification		1. Modified DHCP get in infinite loop when IP set to all zero (0.0.0.0).
Removed		