

Proware Technology Corp.  
 Technical Support Team  
 Firmware Release Notes

**Model: U320 SCSI/FC2G to Serial ATA 12 CHL.  
 (i80321-600)(89230)  
 For: SB-2128SA(T)/FA(T) Series.**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>2.05a</b>	<b>2.06a</b>
<b>Date</b>		<b>August 29, 2005</b>
<b>New</b>		
<b>Fixed</b>		1. Fixed Host cannot access when Array with online-init is in progress. 2. Fixed PCI or SATA error when Array 1 is performing online-init and concurrently creating Array 2. <b>FC:</b> 1. Fixed Dual FC problem on Mac OS X 10.4.
<b>Modification</b>		1. Clear warning message automatically when BBM temperature is under 45'C.
<b>Removed</b>		