

Firmware Release History

Model: iSCSI(1Gbps) x 2 to SATA-II 8/12/16 CHL. (80341/800)(P150C)

Version	Firmware Date	Release Date (MM/DD/YYYY)	Notes
1.1.6	200906251800	08/03/2009	<p>Not compatible with firmware 1.0.0, upgrades from 1.0.0 please backup your data first.</p> <ol style="list-style-type: none"> 1. Added display hard drive firmware on GUI. 2. Added without "initialization" option. 3. Fixed naming with special characters hand up issue. 4. Fixed "Company" and "Product" name disappeared issue. 5. Fixed console LUN more than 255 issue. 6. Fixed abnormal attached 1025th LUN. 7. Fixed long event log did not show complete in console. 8. Fixed RAID5 with strip size 4K stop initialize. 9. Fixed hot plug issue for Hitachi HDE721010SLA330. 10. Fixed WS2003 MSCS issue. 11. The default SNMP events level change to "Warning and Error".
1.1.4	200812121700	01/14/2009	<p>Not compatible with firmware 1.0.0, upgrades from 1.0.0 please backup your data first.</p> <ol style="list-style-type: none"> 1. Added "Filter" for "user" account. 2. Added backend I/O timeout. 3. Added support ping with large MTU. 4. Added UDV/VD block size to 8, 16,

			<p>32 and 64K.</p> <ol style="list-style-type: none"> 5. Added background I/O rate option. 6. Fixed "Time Zone" issue on UI. 7. Fixed error on Windows Server 2008 Cluster (32bit). 8. Fixed CHAP issue on UI. 9. Fixed LUN issue on VMWare ESX with QLA4052. 10. Disk NCQ can be disable. 11. Enable/Disable disk property.
1.1.3p2	200809261100	11/07/2008	<p>Not compatible with firmware 1.0.0, upgrades from 1.0.0 please backup your data first.</p> <ol style="list-style-type: none"> 1. SCSI "persistent reservation" support. 2. Fixed System name include "" GUI issue. 3. Fixed unstable issue when transfer size up to 1Mbytes. 4. Fixed can not logon with CHAP enabled on VMware ESX/ESi 3.5. 5. Fixed system name include "!" issue when import config. 6. Fixed abnormal fans speed. 7. Updated MIB.
1.1.0	200804181300	05/23/2008	<p>Not compatible with firmware 1.0.0, upgrades from 1.0.0 please backup your data first.</p> <ol style="list-style-type: none"> 1. Added French GUI support. 2. Fixed GUI hand on at "Import in progress.." when click config import. 3. Fixed trunk issue on RHAS4. 4. Fixed cannot set spare in console. (RAID 0+1). 5. Changed time zone setting style to Windows like. 6. Changed MTU to Jumbo Frame and for Enable/Disable.

1.0.0	200710181800	11/08/2007	1. Initial release.
-------	--------------	------------	---------------------