

Proware Technology Corp.  
 Technical Support Team  
 Firmware Release Notes

**Model: iSCSI(1Gbps) 4 ports to SAS 16 CHL. (IOP342)  
 For: SB-3164E-G1S3, SB-2124-G1S3 Series.**

	<b>Previous Version</b>	<b>New Version</b>
<b>Version No.(DC)</b>	<b>1.0.3 (200812121700)</b>	<b>1.0.4 (200904161100)</b>
<b>Date</b>		<b>June 16, 2009</b>
<b>New</b>		<ol style="list-style-type: none"> <li>1. Added per VD/RG read-ahead enable/disable.</li> <li>2. Display hard drive firmware on console and web GUI.</li> <li>3. Added LCM password.</li> </ol>
<b>Fixed</b>		<ol style="list-style-type: none"> <li>1. Fixed web GUI hang at "Loading" when naming VD with special characters.</li> <li>2. Fixed too many session login/logout messages when connect to QLogic QLA4052C with 2 or more nodes.</li> <li>3. Fixed VD attach and detach when 'offline'.</li> <li>4. Fixed over 255 LUNs on console.</li> <li>5. Fixed over 1024 LUNs on web GUI.</li> <li>6. Fixed disk shown as 'Free' when upgrade JBOD firmware.</li> </ol>
<b>Modification</b>		<ol style="list-style-type: none"> <li>1. iSCSI node name can not be empty.</li> <li>2. Change default event level to 'Warning' and 'Error' for SNMP.</li> </ol>
<b>Removed</b>		